

International Linear Collider at Fermilab

SMTF Collaboration Meeting

October 5th – 7th, 2005

Working Group 1; Topic 2

"Updates on High Pressure Rinsing, Ultra Pure Water, and Cleanroom Handling"

Speakers: John Mammosser (JLab)

Saeki (KEK)

Detlef Reschke (DESY) - by video?

Discussion leaders: John Mammosser (JLab)

Allan Rowe (FNAL)

- Active particle counting during assembly is important. Instant feedback may be an important procedural change to the current processing schemes employed at the various Labs not currently doing so.
 - KEK and DESY have established that monitoring particle counts during component assembly is critical to their high gradient successes.
- A strong correlation has not been made between the specifics of Ultra Pure Water (UPW) quality, High Pressure Rinse (HPR) parameters and Cleanroom handling procedures and successful cavity tests.
 - SCRF programs that achieve high gradients have quite different processing procedures.
 - Performance consistency at the successful Labs is still a problem even when procedures are carefully followed.

- Process equipment failures are common to all SCRF programs.
 - HPR pumps, UPW quality degradation, Compressed air systems, etc.
- Few, if any predictive indicators or diagnostics are used in the UPW and HPR processing regime to anticipate systematic failures.
 - Current real-time monitoring includes UPW resistivity monitoring, TOC, etc.
- Data on HPR, UPW, and Cleanroom handling is starting to be collected. (JLab/DESY)
 - Data currently being collected includes: pre-rinse water particle count, resitivity, and TOC.

- HPR effectiveness studies are underway at CARE and JLab to study HPR nozzle spray patterns and particle removal rates.
 - An optimized HPR time and flow rate may be discovered along with nozzle geometry and material improvements.
- Post HPR water particle counts are not being performed.
 - A strong correlation in the particles counted from beginning to end of the rinse cycle may determine the HPR time length.

 This 3-day SMTF collaboration meeting was provided a good start on the discussion of these topics. Many more detailed discussions are required to truly get the detailed views from each Lab.

Recommendations

 Labs currently processing and testing SCRF cavities should carefully monitor particles during component assembly. Movement should stop when particle counts get elevated.

 Failure avoidance plans should be considered at existing and future facilities. (parallel HPR systems, etc.)

Recommendations cont...

 Careful failure analysis of each processing element needs to be performed. (Knowing the MTBF of critical components will prevent significant losses in processing time.)

 Develop methods to predict when systems may fail. E.g. DI bottle changes in UPW systems often leads to bacteria and TOC contamination.

Recommendations cont...

- UPW/HPR data should be carefully analyzed to determine process characteristics can be related to resultant cavity performance
- Systematic data (UPW quality, rinse parameters, etc.) taken at the various Labs during processing sequences should be compared to other Labs' data to identify targets for processing improvement.

Recommendations cont...

- An accurate particle count in the drained HPR water needs to be performed as a test of the quality of the HPR cycle.
- A task force should be formed that analyzes and coalesces the state-of-the-art HPR, UPW, and cleanroom handling procedures at all of the leading SCRF Labs. This task force would distill the information into a report to help guide the SCRF community toward repeatable 35-40MV/m cavities.